



भारत सरकार

कार्यपालक अभियन्ता कार्यालय

गुवाहाटी मंडल के लो नि वि

बामुनीमैदान गुवाहाटी - 781021

e-mail Id: eegcdcpwd.ghy@gov.in/eegcdghy@gmail.com



Government of India

O/o the Executive Engineer,

Guwahati Division, CPWD

Bamunimaidan, Guwahati - 781021

मि. संख्या. 23(344)/कार्यपालक अभियन्ता, गु.मंडल/2023-24/560 (हि.)

दिनांक: 21/12/2023

### TO WHOM IT MAY CONCERN

It is certified that the School Building, Staff quarters and Boundary wall of Kendriya Vidyalaya, at BSF Campus, Panbari, Dist. Dhubri, Assam -783339 had been inspected by the Junior Engineer in charge, Dhubri Central Sub Division, CPWD, Dhubri on dated 18.11.2023. During the Inspection no noticeable defects are found and the infrastructures are structurally safe as on date.

सेवा मे / To

The Principal  
Kendriya Vidyalaya Panbari,  
BSF Campus, P.O: Alamganj  
Dist.: Dhubri, Assam- 783339

संदर्भ /Ref.: Your letter F. No. 12/KVP/2022-23/107 dated 15.02.2023

(ई. दि. शा. ठाकुर)

20-12-23

कार्यपालक अभियन्ता/ Executive Engineer,

गुवाहाटीमंडल, Guwahati Division

के. लो . नि. बि., गुवाहाटी-21

CPWD, Guwahati-21

प्रतिलिपि / Copy to

- 1) The Chief Engineer, Guwahati, CPWD, Garchuk, Guwahati-35 for favour of kind information please.
- 2) The Assistant Engineer, Dhubri Central Sub Division, CPWD, Dhubri, Assam for information w.r.t his office letter No 23(04)/AE/DCSD/2023-24/224 dated 19.12.2023.

कार्यपालक अभियन्ता/ Executive Engineer